

# **TradeWinds International, Inc.**

## **KRYSTALSEAL™**

### Limited Warranty of Performance as a Moisture-Barrier, Penetrating Sealant for Raw Concrete

**TradeWinds International, Inc.**, hereby offers a limited warranty of performance on **KrystalSeal™**, a two-component, EPA & SCAQMD VOC-compliant, high-solids, vapor barrier, deep-penetrating, epoxy sealant, according to the following criteria:

- A. Adherence to conditions and directions, as described in the **KrystalSeal™ Data Sheet**, concerning proper elapsed concrete cure time, proper surface preparation; proper material mixing & application; and observation of proper elapsed material cure time, prior to allowable use conditions.
- B. Adherence to conditions and directions for application of an epoxy-compatible adhesive used to adhere the natural or synthetic flooring material selected, as described by the manufacturer of said adhesive, concerning proper adhesive material mixing & application.
- C. Adherence to conditions and directions for application of the natural or synthetic flooring material used, as described by the manufacturer of said flooring material, concerning proper adhesive material installation.

**TradeWinds International, Inc.**, in accordance with the above cited qualifications and conditions, hereby warrants **KrystalSeal™** against moisture-barrier failure for a length of time not to exceed 10-years, or the length of warranty offered by the manufacturer of the epoxy-compatible adhesive used, or the length of warranty offered by the manufacturer of the flooring material used. **TradeWinds Intl., Inc.** will not warrant or accept responsibility for underlying concrete slab failure for any reason, including excessive moisture vapor emissions suppressed within the concrete below **KrystalSeal™**. This warranty does not cover conditions caused by structural failure, seismic action, or circumstances beyond the control of **TradeWinds Intl., Inc.**. Liability is limited to the material replacement cost of the concrete sealant, and the material replacement cost of the immediately affected finished flooring materials only, labor excluded.